

Root Intrusion Sewer Sandy UT Bumble Bee Plumbing Hydro Jet Repair Tree root intrusion is one of the most common causes of sewer line problems in Sandy's established residential neighborhoods, where mature trees that were planted alongside homes built in the 1950s through [Plumber Sandy UT](#) the 1980s have had decades to extend their root systems through the soil and into the clay or cast iron sewer pipes that run beneath the yard. Root tips that enter through pipe joints or cracks in older pipes grow inside the pipe over time, eventually developing into root masses that trap waste, restrict flow, and ultimately cause complete blockages. Bumble Bee Plumbing's camera inspection identifies root intrusions specifically, allowing targeted response rather than guesswork. Hydro jetting is Bumble Bee Plumbing's primary approach to active root intrusion in Sandy sewer lines, using high-pressure water to cut through root masses and flush them downstream. While hydro jetting does not kill the root system, it removes the growth that has accumulated in the pipe and buys time before regrowth creates the same problem again. The regrowth timeline varies based on the tree species, the soil moisture conditions, and the size of the access points the roots are using to enter the pipe. For Sandy sewer lines with significant root intrusion, hydro jetting combined with pipe lining offers a more permanent solution. Cured-in-place pipe lining installs a seamless liner inside the existing pipe that seals the joint gaps and cracks that roots are entering through, denying root access to the pipe interior while restoring structural integrity to the aging pipe.

Bumble Bee Plumbing | 10178 Heytesbury Ln, Sandy, UT 84092 | (385) 205-1833

For root intrusion diagnosis, hydro jetting, and sewer lining in Sandy, UT, call Bumble Bee Plumbing at (385) 205-1833. Camera inspection is included in the diagnosis.

Bumble Bee Plumbing

10178 Heytesbury Ln, Sandy, UT 84092

(385) 205-1833

Plumber | Sandy, UT